



Picture 1 – Sunset Lake Farm, 80 Middle Rd., Alburgh, VT – 08/13/14
Concrete sump/pit and manure transfer pump.



Picture 2 – Sunset Lake Farm, 80 Middle Rd., Alburgh, VT – 08/13/14
Main farm manure pit (at capacity).



Picture 3 – Sunset Lake Farm, 80 Middle Rd., Alburgh, VT – 08/13/14
Location where manure is overflowing the manure pit.



Picture 4 – Sunset Lake Farm, 80 Middle Rd., Alburgh, VT – 08/13/14
Grassy bank and slope below location where manure was overflowing the main pit.



Picture 5 – Sunset Lake Farm, 80 Middle Rd., Alburgh, VT – 08/13/14
Semi-solids pile from the calf hutches and maternity area.



Picture 6 – Sunset Lake Farm, 80 Middle Rd., Alburgh, VT – 08/13/14
Newer concrete retaining wall in silage area.



Picture 7 – Sunset Lake Farm, 80 Middle Rd., Alburgh, VT – 08/13/14
Edge of the silage storage area where runoff collects and flows off the pad.



Picture 8 – Sunset Lake Farm, 80 Middle Rd., Alburgh, VT – 08/13/14
Location where silage pad runoff flows into a grassy field.



Picture 9 – Sunset Lake Farm, 80 Middle Rd., Alburgh, VT – 08/13/14
Grassy area between the silage pad runoff area and drainage ditch on the east side of the farm.